




M12 9912 MRRD

Accessories M12



Marking ring for overmolded M12 connectors, red

M12 9912 MRRD



Environmental conditions

Temperature range -40/+100 °C

Materials

Color ring POM

Associated products

Accessories

| | | |
|---|---|---|
| ☞ 1200 ... 0... | ☞ 1200 ... 0... | ☞ 1200 ... 0... |
| ☞ 1200 ... 3... | ☞ 1200 ... 3... | ☞ 1200 ... 3... |
| ☞ 1205 ... 0... | ☞ 1205 ... 0... | ☞ 1205 ... 0... |
| ☞ 1205 ... 3... | ☞ 1205 ... 3... | ☞ 1205 ... 3... |
| ☞ 1206 ... L1 0... | ☞ 1206 ... L1 0... | ☞ 1206 ... L1 0... |
| ☞ 1206 ... L1 3... | ☞ 1206 ... L1 3... | ☞ 1206 ... L1 3... |
| ☞ 1206 ... L2 0... | ☞ 1206 ... L2 0... | ☞ 1206 ... L2 0... |
| ☞ 1206 ... L2 3... | ☞ 1206 ... L2 3... | ☞ 1206 ... L2 3... |
| ☞ 1210 ... 0... | ☞ 1210 ... 0... | ☞ 1210 ... 3... |
| ☞ 1210 ... 3... | ☞ 1210 0800 ... 3... | ☞ 1210 0800 ... 3... |
| ☞ 1210 0806 ... L1 3... | ☞ 1210 0806 ... L1 3... | ☞ 1210 1200 ... 0... |
| ☞ 1210 1200 ... 0... | ☞ 1210 1200 ... 0... | ☞ 1210 1200 ... 3... |
| ☞ 1210 1200 ... 3... | ☞ 1210 1200 ... 3... | ☞ 1210 1205 ... 3... |
| ☞ 1210 1205 ... 3... | ☞ 1210 1205 ... 3... | ☞ 1210 1206 ... L1 0... |
| ☞ 1210 1206 ... L1 0... | ☞ 1210 1206 ... L1 0... | ☞ 1210 1206 ... L1 3... |
| ☞ 1210 1206 ... L1 3... | ☞ 1210 1206 ... L1 3... | ☞ 1210 1206 ... L2 0... |
| ☞ 1210 1206 ... L2 0... | ☞ 1210 1206 ... L2 0... | ☞ 1210 1206 ... L2 3... |
| ☞ 1210 1206 ... L2 3... | ☞ 1210 1206 ... L2 3... | |

M12 9912 MRRD

| Designation | Pole Number | PU (Pieces) | MDQ (Pieces) |
|-------------|-------------|-------------|--------------|
| 9912 MRRD | - | 20 | 100 |

Packaging:
in a plastic bag